



TA1600/2400/3200 V4

Release Notes

Yeastar Information Technology Co., Ltd.

Firmware 49.0.0.22

Date: April 25, 2024


Optimization

- Added support for importing configurations of port data (Path: **Gateway** → **Port List** → **Port List**).



<input type="checkbox"/>	Port	Name	Call Waiting	DND	Always Forward	No Answer Forward	Busy Forward	
<input type="checkbox"/>	1	test	no	no	no	yes	yes	
<input type="checkbox"/>	2	test2	no	no	no	yes	yes	

- Added support for exporting and importing Dial Pattern templates (Path: **Gateway** → **VOIP Settings** → **Dial Pattern Template**).



Template ID: 1
Template Name: DialPatternTemplate1

Dial Pattern

Dial Pattern	Strip	Prepend	
<input type="text"/>	<input type="text"/>	<input type="text"/>	

Bug fix

- Fixed the remote management issue: Failed to connect to the Remote Management platform.

Firmware 49.0.0.18

Date: November 17, 2021

First Release.

What is new in TA V4 (compared with TA V3):

Firmware Optimization

- Do not support G723 Codec.
- Optimized Fax feature: TA V4 supports fax processing using software, which can implement multiple fax lines sending and receiving faxes concurrently.
- Added feature of **Loop Current Disconnect** on FXS port.
When TA gateway detects a loop current on the FXS port, the call on this port will be hung up.

Hardware Optimization

- Removed DSP module.
- Increased storage volume for Flash and RAM.

Items	TA V3	TA V4
Flash	NAND Flash 512MB	eMMC 4GB
RAM	LPDDR 512MB	DDR4 1GB